Enable Interrupt

0

EI

D10 = RPM (based on 0.1 rpm)

1   M1000

DDIV   K6000000   D0   D10

Normally o
pen contac
t (a conta
ct). This

15

FEND

Interrupt procedure (X2 rising edge)
D0 = mark to mark time (based on 0.1 ms)

16   I201   M1000

RST   M1015

Normally o
pen contac
t (a conta
ct). This

High-speed
timer act
ivates

MOV   D1015   D0

0~32,767(u
nit: 0.1ms
) addition
 type of h

RST   D1015

0~32,767(u
nit: 0.1ms
) addition
 type of h

SET   M1015

High-speed
 timer act
ivates

30

IRET

31

END